

[Issue Descriptions]: BIOS issues caused by plugging in RS232 loopback

Loop back test does not allow at BIOS level. At BIOS level we default enable console redirection to display BIOS UI at COMPORT. Client can disable it to solve the issue.

