

[Issue Descriptions]: Suspected water vapor inside the panel at high and low temperatures

Suggest contacting sales and proposing optical bonding requirements to avoid air flow and moisture entrainment in the panel