

[Issue Descriptions]: Ghost touch (Capacitive)

For the 'ghost touch' issue on capacitive touchscreens, the following improvement strategies can be considered:

1. Software Updates and Calibration: Address potential sensitivity issues through software updates and calibration.
2. Environmental Management: Ensure the surrounding environment is clean and free from interference, such as avoiding static electricity or foreign objects touching the screen surface.
3. Hardware Inspection: Check the hardware condition of the capacitive touchscreen to ensure no faulty or damaged components.

These measures help to reduce or eliminate the 'ghost touch' phenomenon on capacitive

touchscreens, enhancing their accurate touch functionality.

If none of the issues can be resolved, please contact sales or CS.