

## **[Issue Descriptions]: The panel used turns black under strong light**

1. It is possible that the heat of the sunlight has exceeded the panel specifications.
2. In some cases, when sunlight does not reach the panel, the screen gradually returns to normal. Usually, this exceeds the panel specifications.
3. If irreversible panel blackening occurs, please contact sales or CS to send it back for repair.